

# Using your new DVP-NC555ES Upgraded SACD Player

The quality of sound from your upgraded Sony DVP-NC555ES SACD/DVD player is a far cry from that of the stock unit. In order to receive the best possible sound from your unit a few guidelines must be addressed.



- **Burn-in:** The unit must be allowed **at least 120 hours** of playing time to “burn in” before optimum sound quality will be achieved. Your upgraded unit has already been running for 24 hours before it was returned to you, but even the new LClock board takes at least 48 hours of running time to burn in. Please allow the unit time to burn in before making any subjective observations.
- **Configuration:** The unit’s software and filtering settings have been configured for optimum CD and SACD performance after it was modified. You may wish to experiment with different settings.
- **Cables:** The quality of your interconnect cables can also have a major effect on the sound quality. The use of low quality cables may detract from the sound that this mod is trying to accomplish. If the unit doesn’t sound right, then try different interconnects. Remember that interconnects sound different with each player/preamp combination.

If you have any problems with the mods feel free to contact me immediately through my website: [www.SACDmods.com](http://www.SACDmods.com) All modifications are warranted from defects for 1 year from the date of installation.\*



\* Not responsible for damage due to electrical surges or lightning damage. Not responsible for customer negligence. Operation of this unit must be conducted in the same manner as described in the Sony owner’s manual.